Scope or	Property is: Single Far			2.V	☐ Other ☐		
Date:	3/14/2016	nily 🗹	Duple	ΞX	L Ottlei L		
			afetvissi	IES	The City of Milwaukee, the Redevelopmen	t Authority, and their repre	contativos
ake no respo	nsibility for problems discovered	after the ins	spection (date	, or for omissions through error or oversight		
work required	by private lenders, insurance co	mpanies, 01	by the F	ede	ral Block Grant or HOME programs.		
Exterior (Condition Report						
Location Site	Required Work Landscaping	n/a ✓	Yes [7	Note/Comments Self Help	\$	Cost
J.10	Steps/Handrails	n/a ☑				\$	
	Service walks	n/a 🗌		√		\$	1,800.00
	Fencing	n/a ✓				\$	•
	Parking	n/a 🗌	Yes	1		\$	3,500.00
	Retaining walls	n/a ☑	Yes [\$	
	Other	n/a _] Yes			\$	
	Other	n/a 🗆	Yes [\$	
Garage	Singles: repair	n/a □	Yes [\$	
	Shingles: Roof over existing	n/a \square	Yes [\$	
	Shingles:Tear off & re-roof	n/a \square		<u> </u>		\$	
	Gutters/downspouts		Yes [\$	
	Flashing	n/a 🗌	Yes [\$	
	Eaves	n/a 🗌	Yes [\$	
	Siding	n/a 🗌	Yes [\$	
	Doors	n/a _	Yes [\$	
	Windows	n/a 🗌	Yes [\$	
	Slab	n/a 🗌	Yes [\$	
	Paint	n/a 🗌	Yes [\$	
	Electrical	n/a 🗌	Yes [\$	
	Other	n/a 🗌	Yes [\$	
Porches	Roof	n/a ✓	Yes [\$	
	Deck-upper	n/a 🗸	Yes [\$	
	Decklower	n/a	Yes [√		\$	2,880.00
	Steps/handrails	n/a _✓	Yes [_	\$	
	Ceiling	n/a _✓	Yes [\$	
	Guardrails	n/a ☑	Yes [\$	
	Structural	n/a 🔽	Yes [\$	
	Paint	n/a	Yes [J		\$	450.00

n/a Yes

Other

House

Chimney	n/a 🗸 Yes 🗌	\$
Shingles: repair	n/a ✓ Yes 🗌	\$
Shingles: Roof over existing	n/a ✓ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a Yes including structural	\$ 12,000.00
Gutters/downspouts	n/a 🗌 Yes 🗸	\$ 1,100.00
Flashing	n/a ✓ Yes 🗌	\$
Eaves	n/a Yes 🗸 fascia/soffit	\$ 800.00
Siding	n/a 🗸 Yes 🗌	\$
Storm Doors	n/a 🗸 Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 700.00
Storm Windows	n/a ✓ Yes 🗌	\$
Prime ("main") Windows	n/a ☐ Yes ✓	\$ 2,480.00
Paint	n/a ☐ Yes ✓	\$ 2,800.00
Foundation	n/a ☑ Yes □	\$
Electrical	n/a Yes new service	\$ 1,000.00
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:*

29,510.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	undition Report Unit: Entire unit (single family) Upper unit of duplex	✓ □				Lower unit of duplex Other		
Mechanical Heating	Required Work	_						
	Repair/replace boiler	n/a	✓	Yes		_	9	\$
	Repair radiation	n/a	V	Yes				\$
	Repair/replace furnace	n/a	V	Yes		_		\$
	Repair ductwork	n/a	√	Yes		_	(\$
	Replace thermostat	n/a	7	Yes			(\$
	Repair/replace grilles	n/a	4	Yes		_	5	\$
Electrical	Tune boiler/furn. insp ht exchange	n/a		Yes	V			\$ 350.00
Licotrioui	Repair/replace receptacles	n/a		Yes	√	_	(\$ 800.00
	Repair/replace switches	n/a		Yes	4	_	\$	\$ 800.00
	Repair/replace fixtures	n/a		Yes	V	_	(\$ 800.00
	Install outlets and circuits	n/a	1	Yes				\$
	Install outlets and circuits	n/a	1	Yes		-	9	\$
	Install outlets and circuits	n/a	√	Yes			(\$
	Install outlets and circuits	n/a	4	Yes		=	(\$
	Upgrade service	n/a		Yes	1	=		\$ 1,750.00
	Other	n/a		Yes	7	permit	(\$ 85.00
	Other	n/a		Yes			(\$
Plumbing	Repair/replace kitchen sink	n/a		Yes		_	(\$
	Repair/replace kitchen sink fauce	n/a		Yes		_		\$
	Repair/replace tub	n/a		Yes		=	(\$
	Repair/replace tub faucet	n/a		Yes		_	9	\$
	Repair/replace toilet	n/a		Yes				\$
	Repair/replace lavatory	n/a		Yes			(\$
	Repair/replace lavatory faucet	n/a		Yes			9	\$
	Repair/replace wash tub	n/a		Yes			(\$
	Repair/replace wash tub faucet	n/a		Yes		_	(\$
	Other	n/a		Yes	4	permit	(\$ 85.00
	Repair drain/waste/vent piping	n/a		Yes	V	-	(\$ 700.00
	Repair water piping	n/a		Yes	√		(\$ 700.00
	Repair/replace water heater	n/a		Yes	1		(\$ 1,300.00
	Other	n/a		Yes	V	complete kitchen	(\$ 1,455.00
	Other	n/a		Yes	1	complete bathroom	\$	\$ 2,170.00

Windows							
	Replace broken glass	n/a 🔽	Yes		_	\$	
	Repair or replace sash	n/a 🔽	Yes		_	\$	
Doors	Deneis en mente en de en-	/	Vaa		=	Ф	050.00
	Repair or replace doors	n/a 📙	Yes	7	_	\$	950.00
	Repair or repl. locks/latches	n/a 🔲	Yes	1	Self Help	\$	275.00
Walls/Ceilin	Repair or repl. @ defective	n/a 🔲	Yes	7		\$	2,400.00
Paint	Repair or repl. @ defective	n/a □	Yes	V		\$	1,200.00
Fire Safety						*	,
rife Salety	Install smoke/CO alarm:bsmt.	n/a 🔲	Yes	V	Self Help	\$	85.00
	Install smoke/CO alarm: 1st flr.	n/a 🔲	Yes	y	Self Help	\$	170.00
	Install smoke/CO alarm: 2nd flr.	n/a 🔲	Yes	y	Self Help	\$	170.00
Handrails	Repair/replace defective	n/a _	Yes	7	Self Help	\$	250.00
Stairs	Repair defective	n/a □	Yes	7		\$	870.00
Floors							
Other	Repair defective	n/a 📙	Yes	✓		\$	2,000.00
		n/a 🗌	Yes			\$	
	-	n/a 🗌	Yes			\$	
		n/a 🗌	Yes			\$	
		n/a 🔲	Yes		-	\$	
					Interior: Estimated Cost:	\$	19,365.00
					Total Exterior and Interior Cost:*	\$	48,875.00

Inspected by: Tom Frank Date: 3/10/16

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.